




National Fire Equipment Ltd.

Febco 805Y, 805YB, 805YS
3/4" - 2" Double Check Assembly



| Item Description | Style | Size | 3/4" - 1 1/4" | 1 1/2" & 2" |
|---|-------|--------|---------------|-------------|
| RUBBER KIT FOR BOTH CHECKS (8, 10, 2 ea.) | Y, YB | Part # | 905042 | 905053 |
| | YS | Part # | 905042S | 905053S |
| SINGLE CHECK REPAIR KIT (valve has two checks) (8-12, 1 ea.) | Y, YB | Part # | 905044 | 905055 |
| | YS | Part # | 905044S | 905055S |
| DOUBLE CHECK KIT w/SPRINGS (8-13, 2 ea.) | Y, YB | Part # | 905242 | 905243 |
| | YS | Part # | 905240 | 905241 |
| CHECK SPRINGS | Y, YS | Part # | 630115 | 630118 |
| | YB | Part # | 630167 | N/A |

805, 835B Double Check Assembly

Contact FEBCO Representative for information on components for these older designs. To replace the entire assembly (recommended) use FEBCO Model 850 Double Check.