




National Fire Equipment Ltd.

Febco 805, 805D, 805TD / 806YD
2 1/2" - 10" Double Check / Double Check Detector Assemblies



Item Description	Style	Size	2 1/2"	3"	4"	6"	8"	10"
RUBBER PARTS Items 11, 14, 50	805, 805D,	Part #	905059	905060	905061	905062	905063	905064
	805YD, 806YD	List \$	\$42.10	\$62.40	\$95.20	\$135.80	\$185.80	\$218.60
SINGLE CHECK ASSEMBLY Items 3, 4.1, 5, 6, 7, 7.1, 7.2, 9, 11, 15, 50	805YD	Part #	905086	905088	902467	902469	902471	902473
		List \$	\$619.80	\$658.80	\$881.60	\$1,413.00	\$2,399.70	\$3,914.10
	806YD	Part #			902514	902515	902516	902517
		List \$			\$966.50	\$1,539.40	\$2,615.20	\$4,306.00
SEAT KIT Items 2, 2.1 & 12.1	805YD	Part #	902386YD	902385YD	902384YD	902383YD	902382YD	902381YD
	806YD	List \$	\$301.40	\$335.70	\$496.60	\$655.10	\$1,067.90	\$1,328.60
GATE MOUNTING KIT (both ends) Items 16, 17, 17.1	805, 805D,	Part #	905036	905037	905038	905039	905040	905041
	805YD, 806YD	List \$	\$114.00	\$115.60	\$238.90	\$271.70	\$281.00	\$457.50
COVER ASSEMBLY Items 4, 4.1, 14 & Aircock (not shown)	805YD,	Part #	902497	902498	902499	902500	902501	902502
	806YD	List \$	\$330.90	\$366.90	\$423.40	\$557.30	\$1,314.60	\$1,314.60



805, 805D Double Check Assemblies

Contact FEBCO Representative for information on unlisted components for these older designs.
 To replace the entire assembly (recommended) use FEBCO Model 850 Double Check Assembly with Spool Adapter
 (see FEBCO Backflow Prevention Price List).