




# National Fire Equipment Ltd.

## Febco 850, 856 2 1/2" - 10" Double Check / Double Check Detector Assemblies



Item Description	Style	Size	2 1/2" & 3"	4"	6"	8" & 10"
DISC ASSEMBLY Items 6, 16, 17. (10", Item 6 only)	ALL	Part #	905182	905153	905154	905155
		List \$	\$126.50	\$126.50	\$157.70	\$295.10
SINGLE CHECK MODULE Items 5.1, 7, 8, 9, 9.1, 10, 11, 12, 12.1	850	Part #	905142	905143	905144	905145
		List \$	\$123.40	\$135.80	\$164.00	\$185.80
	856	Part #	905147	905148	905149	905150
		List \$	\$126.50	\$140.50	\$171.30	\$190.50
CHECK REPLACEMENT KIT Items 2.1, and 3 - 17	850	Part #	905527	905534	905537	905539
		List \$	\$583.90	\$658.80	\$861.80	\$1,099.10
	856	Part #	905529	905536	905538	905541
		List \$	\$587.00	\$663.50	\$871.70	\$1,192.80
SEAT RING / ARM ASSEMBLY Items 3, 3.1, 3.2, 3.4, 4, 4.1, 4.2, 5	ALL	Part #	905157	905158	905159	905160
		List \$	\$206.10	\$215.50	\$310.80	\$340.40
RUBBER PARTS KIT Items 2.1, 3.1, 6, 15, 26, 35, 35.1, 45, 45.1	ALL	Part #	905249	905163	905164	905165
		List \$	\$245.10	\$245.10	\$338.80	\$736.90
COVER ASSEMBLY Items 2, 2.1, 15	WITH BULKHEAD FITTING	Part #	905167	905168	905169	905170
		List \$	\$206.10	\$234.20	\$271.70	\$310.80
	TAPPED	Part #	905376	905377	905378	905379
		List \$	\$206.10	\$234.20	\$271.70	\$310.80
BULKHEAD FITTING FOR COVER* Items 43.1, 45.1, 46.1, 47.1	850	Part #	905275		905277	
		List \$	\$26.50		\$36.00	
	856	Part #	905277			
		List \$	\$36.00			
BULKHEAD FITTING FOR BODY* Items 43, 45, 46, 47	850	Part #	905276		905277	
		List \$	\$32.80		\$36.00	
	856	Part #	905277			
		List \$	\$36.00			



\*Bulkhead fittings are not furnished on late models. Very early productions of Model 856 may require a different bulkhead fitting. Consult your FEBCO representative for assistance.